

Number	System	Description	Person
AP-350-990-00	Forward Calorimeter	Procedure for Withdrawal and Reinsertion	S. Metcalfe
AP-350-990-01	BaBar Detector	Procedure for Vertical Position Adjustment	
AP-350-990-02	BaBar Detector	Procedure for Yaw Adjustment	
AP-350-990-03	Forward End Doors	Procedure for Opening and Closing	J. Krebs
AP-350-990-04	Backward End Doors	Procedure for Opening and Closing	J. Krebs
AP-350-990-05	Backward End Plug	Procedure for Removal and Reinsertion	J. Krebs
AP-350-990-06	Flux Return	Procedure for Removal/Installation of FWD Lower Corner Blocks	J. Krebs
AP-350-990-07	Flux Return	Procedure for Removal/Installation of FWD Upper Corner Blocks (2004)	J. Krebs
AP-350-990-08	Flux Return	Procedure for Removal/Installation of FWD Upper Center Gap Plate	J. Krebs
AP-350-990-09	Flux Return	Procedure for Removal/Installation of FWD Lower Center Gap Plate	J. Krebs
AP-350-990-10	Flux Return	Procedure for Removal/Installation of FWD Lower Flux Bar	J. Krebs
AP-350-990-11	Flux Return	Procedure for Removal/Installation of FWD Upper Flux Bar	J. Krebs
AP-350-990-12	Flux Return	Procedure for Removal/Installation of Side Gap Plates	J. Krebs
AP-350-990-13	Flux Return	Procedure for Removal/Installation of FWD Lower Corner Block Adaptor	J. Krebs
AP-350-990-14	Flux Return	Procedure for Removal/Installation of FWD Solenoid Support Arm	J. Krebs
AP-350-990-15	Flux Return	Procedure for Removal/Installation of BWD Lower Corner Blocks	J. Krebs
AP-350-990-16	Flux Return	Procedure for Unbolting/Bolting Barrel Corner Blocks	L. Dittert
AP-350-990-17	General	Checklist for Overhead 50 Ton Bridge Crane	J. Krebs
AP-350-990-18	Flux Return	Procedure for Corner Block Handling	J. Krebs
AP-350-990-19	EMC	Procedure for Installing the EMC Load Transfer Tooling	L. Dittert
AP-350-990-20	EMC	EMC Forward Load Transfer Procedure	R.F. Boyce
AP-350-990-21	Flux Return	Procedure for Removal/Installation of Forward End Plug	J. Krebs
AP-350-990-22	Flux Return	Procedure for Removal/Installation of FWD Upper Corner Blocks (2006)	J. Krebs
AP-350-990-23	Flux Return	Procedure for Removal/Installation of FWD Middle Corner Blocks	J. Krebs
AP-350-990-24	Flux Return	Procedure for Removal/Installation of FWD Middle Corner Block Adaptor	J. Krebs
AP-350-990-25	EMC	Procedure for Removal/Installation of FWD EMC Flexible Support Arms	J. Krebs
AP-350-990-26	Flux Return	Procedure for Removal/Installation of FWD Side Barrel Flux Bars	J. Krebs