

Task or Employee: Check/Repair LST Gas Lines Routine Non-routine

Retention: Completed Routine JHAMs are retained by the employee and supervisor. Non-routine JHAMs are retained until the task is fully closed out. In the case of an accident, the form is to be retained for use by the review team. Complete instructions and supporting information is available at <https://www-internal.slac.stanford.edu/esh/SLACsafety/jham/>. Enter information into boxes which will expand to accommodate whatever length of text is entered. Once this JHA is complete, all participants should sign in the Acknowledgement section. Add rows by placing cursor in the right box of the last row and entering a tab.

Sequence of Basic Job Steps	Potential Hazards	Controls & Recommended Actions
Checking gas connections at Forward East side of detector. - Don harness for climbing onto raised platform - Attach harness to inertial reel - Climb onto platform - Perform required gas tightness checks - Climb off of platform - Remove harness	- Fall from platform that is raised about 5 feet from floor	<i>Harness required.</i>

Acknowledgements	Print Name	Signature or Initialed	Date
Supervisor:			
Participant:			